

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210

Box 145801

Salt Lake City, Utah 84114-5801

Telephone: (801) 538-5291

Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) Jan 2004 To (mo./yr.) December 2004
 2. DOGM File Number (Mine No): S 12710029
 3. Mine Name: Denny's Mine #3
 4. Mineral(s) Mined (or permitted to mine): Marble
 5. Type of mine ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
____ 1/4, SE 1/4, SW 1/4, Section 9, Township 23 S, Range 13 W
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
 7. Name of Operator or Company: Daniel Land - Virginia Schre
 8. Permanent Street Address: POB 878
City, State, Zip: Fillmore, UT 84631
Phone: 435-743-6501 Fax: _____
 9. Company Representative (or designated operator):
Name: Virginia Schre
Title: owner
Business Address: POB 878
City, State, Zip: Fillmore, UT 84631
Phone: 435-743-6501 Fax: _____
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? 10 tons

Tr 1/28/04

RECEIVED

JAN 23 2004

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

10 tons of marble was removed from surface

5. How much **additional acreage** was disturbed during the past year? Less than 1

6. How much acreage was **reclaimed** during the past year? 0

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

8. What is the **total** disturbed acreage of entire project at years end? Less than 1 acre

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Continued surface mining for marble

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

VIRGINIA C. GEHRE

Title of Operator:

owner

Signature of Operator:

Virginia Gehre

Date:

1-20-03